


Series 16i/18i/21i/20i-A Maintenance Manual, 63005EN

1 Slot Cabinet, 60MM wide

2 Fans (A90L-0001-0385#C)
in “Fan Unit” (A02B-0265-C101)
Individual Fans in this “Fan Unit”
DO NOT have connectors, both
terminate in a common connector.
We recommend replacing the “Fan
Unit” rather than individual fans.
The plastic mounting tabs for the
connector may be easily broken.



2 Slot Cabinet, 112MM wide

1 Fan (A90L-0001-0488)
in “Fan Unit”(A02B-0260-C021)
We recommend replacing the “Fan
Unit” rather than individual fans.
The plastic mounting tabs for the
connector may be easily broken.

QUESTIONS?

