

6.32
ALARM 930
(CPU ERROR)

CPU error (abnormal interrupt) has generated.

Causes and Remedies

Main CPU board is faulty

An interrupt which will not occur during usual operation has generated. Peripheral circuit of the CPU may be abnormal. Change the main CPU board. If operation is performed normally by power off and on, noise may be a cause. Refer to Subsec. 2.3.13 Action Against Noise.